

Sealand Aviation Ltd. Price List

Transport Canada STC	FAA STC		Part Number	Kit price	Installation Cost by Sealand	Average Time for installation by our Customers	Application
	SA90-2	SA00094NY					
Cabin Extension Kit *			SAL-2F-ECW - Config 2	\$ 16,250.00 /kit	\$ 9,800.00 *	100.00 Hrs	DHC-2
Alaska Door Modification *	SA90-2	SA00094NY	Includes Cabin Extension Kit *	SAL-2F-ECW - Config 3	\$ 32,500.00 /kit	\$ 19,600.00 *	200.00 Hrs
Alaska Door Retro Kit *	SA90-2	SA00094NY	For previously installed Cabin Extension Kit *	SAL-2F-ECW - Retro	\$ 21,000.00 /kit	\$ 14,700.00 *	150.00 Hrs
Float Ladder Kit				SAL-2D-6000	\$ 950.00 /each		DHC-2 With Alaska Door
Inside Door Latch			Rear (Standard Alaska Door)	SAL-2D-7300-2	\$ 1,500.00 /each		DHC-2 With Alaska Door
SS Elevator Trim Push Rod Kit	SA91-15	SA1015NE		SAL-2T-47C	\$ 775.00 /pair		DHC-2
Front Fuselage Struts	SA99-203	SA01645NY		SAL 9000	\$ 1,200.00 /each	20.00 Hrs/side	DHC-2
Basic Med STC - US ONLY		SA022605AK			\$ 1,000.00 kit		DHC-2 USA ONLY
Wing Tip Tanks	SA01-22	SA01300NY		SAL-10128-1 /-2	\$ 14,000.00 /pair		DHC-2
Beaver Jump Seats	SA01-74	SA01380NY	Complete Set	SAL-20-12	\$ 5,000.00 /kit		DHC-2
			Left Seat	SAL-10176-1	\$ 1,375.00 /each		DHC-2
			Right Seat	SAL-10176-2	\$ 1,375.00 /each		DHC-2
			Center Seat	SAL-10186	\$ 1,375.00 /each		DHC-2
			Rear Bench	SAL-10185	\$ 1,200.00 /each		DHC-2 With Cabin Extension Kit
Jump Door & Step	SA11-68		Jump Door **	1103-1001	\$ 4,500.00 /kit		Cessna 182
			Step (Not incl. Graphic)	1103-0001	\$ 1,750.00 /kit		Cessna 182
Engine Instrument Panel Mod	SA03-85	SA01876NY		SAL-20250	\$ 600.00 Exchange		DHC-2
Holmes Extended Engine Mount	SA04-71	SA2100NY		HAP 033001	\$ 11,000.00 Exchange \$ 1,000.00 Core		DHC-2
West Coast Window		SA02441SE		SAL-2W-ECW-1 /-2	\$ 1,500.00 /side	\$ 1,900.00 /side *	20.00 Hrs/side
5250 Float Mod Kit	SA04-129 / SF04-3	SA02425NY / SQ02296NY		5250 MOD KIT	\$ 12,500.00 /kit	\$ 28,500.00 ***	400.00 Hrs
5475 Float Mod Kit	SF16-105			5475 MOD KIT	\$ 14,375.00 /kit	\$ 31,350.00 ***	450.00 Hrs
Replacement Hammock Seat Support Instalation	SA18-29	SA04154NY					
PDA Web Plate				SAL-C2-FS-3783	\$ 800.00 /each		DHC-2
PDA Tie Bar, Upper, DHC				SAL-C2-FS-2255-ND	\$ 1,650.00 /each		DHC-2
PDA Tie Bar, Lower, DHC				SAL-C2-FS-2253-ND	\$ 1,650.00 /each		DHC-2
PDA Bushing, Front Tie Bar				SAL-C2-FS-779	\$ 200.00 /each		DHC-2
PDA Bushing, Tie Bar			For Aircraft on Floats	SAL-58-S-942	\$ 230.00 /each		DHC-2
PDA Cables- DHC-2			Cable – Aileron in cabin LH (long cable)	SAL-C2-CF-1121A	\$ 185.00 /each		DHC-2 (OEM Part Numbers) C2CF1121A, C2CF1125A
			Cable – Aileron in cabin RH (short cable)	SAL-C2-CF-1133A	\$ 180.00 /each		C2CF1133A, C2CF1131A, C2CF607A
			Cable – Rudder Control aft (post mod)	SAL-C2-CF-1235A	\$ 185.00 /each		C2CF1235A, C2CF11237 ND
			Cable – Rudder Trim Aft	SAL-C2-CF-1443A	\$ 365.00 /each		C2CF1443A
			Cable – Elevator Trim Tab Fwd	SAL-C2-CF-1567A	\$ 170.00 /each		C2CF1567AND, C2CF1563A
			Cable – Rudder Trim Fwd	SAL-C2-CF-1569A	\$ 170.00 /each		C2CF1569AND, C2CF1461A
			Cable – Rudder Fwd	SAL-C2-CF-741A	\$ 180.00 /each		C2CF741A, C2CF739ND
			Cable – Rudder Aft (pre-mod)	SAL-C2-CF-745A	\$ 180.00 /each		C2CF745A, C2CF743ND
			Cable – Aileron in wing	SAL-C2-CF-805	\$ 185.00 /each		C2CF805, C2CF809A
			Cable – Elevator upper	SAL-C2-CF-817A	\$ 180.00 /each		C2CF817AND, C2CF813A
			Cable – Elevator lower	SAL-C2-CF-819A	\$ 180.00 /each		C2CF819AND, C2CF815A

All prices quoted in Canadian Dollars, Taxes and freight not included in price.

* Installation does not include paint or upholstery, or the cost of re-locating the battery (if necessary).

** Sealand must do some work on customer's door. Does not include rear seatbelt anchors.

*** Installation does not include paint, or repairs required for proper install of kit.