

**Sealand Aviation Ltd. Price List**

	<i>Part Number</i>	<i>Kit price</i>	<i>Installation Cost by Sealand</i>	<i>Average Time for installation by our Customers</i>	<i>Application</i>
<b>Cabin Extension Kit *</b>	SAL-2F-ECW - Config 2	\$ 16,250.00 /kit	\$ 9,800.00 *	100.00 Hrs	DHC-2
<b>Alaska Door Modification *</b>	Includes Cabin Extension Kit * SAL-2F-ECW - Config 3	\$ 32,500.00 /kit	\$ 19,600.00 *	200.00 Hrs	DHC-2
<b>Alaska Door Retro Kit *</b>	For previously installed Cabin Extension Kit * SAL-2F-ECW - Retro	\$ 21,000.00 /kit	\$ 14,700.00 *	150.00 Hrs	DHC-2
<b>Float Ladder Kit</b>	SAL-2D-6000	\$ 950.00 /each			DHC-2 With Alaska Door
<b>Inside Door Latch</b>	Rear (Standard Alaska Door) SAL-2D-7300-2	\$ 1,500.00 /each			DHC-2 With Alaska Door
<b>SS Elevator Trim Push Rod Kit</b>	SAL-2T-47C	\$ 660.00 /pair			DHC-2
<b>Front Fuselage Struts</b>	SAL 9000	\$ 1,200.00 /each		20.00 Hrs/side	DHC-2
<b>Wing Tip Tanks</b>	SAL-10128-1 / -2	\$ 14,000.00 /pair			DHC-2
<b>Beaver Jump Seats</b>	Complete Set SAL-20-12	\$ 5,000.00 /kit			DHC-2
	Left Seat SAL-10176-1	\$ 1,375.00 /each			DHC-2
	Right Seat SAL-10176-2	\$ 1,375.00 /each			DHC-2
	Center Seat SAL-10186	\$ 1,375.00 /each			DHC-2
	Rear Bench SAL-10185	\$ 1,200.00 /each			DHC-2 With Cabin Extension Kit
<b>Jump Door &amp; Step</b>	Jump Door ** 1103-1001	\$ 4,500.00 /kit			Cessna 182
	Step (Not incl. Graphic) 1103-0001	\$ 1,750.00 /kit			Cessna 182
<b>Engine Instrument Panel Mod</b>	SAL-20250	\$ 600.00 Exchange			DHC-2
<b>Holmes Extended Engine Mount</b>	HAP 033001	\$ 11,000.00 Exchange \$ 1,000.00 Core			DHC-2
<b>West Coast Window</b>	SAL-2W-ECW-1 /-2	\$ 1,500.00 /side	\$ 1,900.00 /side *	20.00 Hrs/side	DHC-2 With Cabin Extension Kit
<b>5250 Float Mod Kit</b>	5250 MOD KIT	\$ 12,500.00 /kit	\$ 28,500.00 ***	400.00 Hrs	EDO 4580
<b>5475 Float Mod Kit</b>	5475 MOD KIT	\$ 14,375.00 /kit	\$ 31,350.00 ***	450.00 Hrs	EDO 4930
<b>PDA Cables- DHC-2</b>	Cable – Aileron in cabin LH (long cable) SAL-C2-CF-1121A	\$ 145.00 /each			DHC-2 (OEM Part Numbers) C2CF1121A, C2CF1125A
	Cable – Aileron in cabin RH (short cable) SAL-C2-CF-1133A	\$ 140.00 /each			C2CF1133A, C2CF1131A, C2CF607A
	Cable – Rudder Control aft (post mod) SAL-C2-CF-1235A	\$ 145.00 /each			C2CF1235A, C2CF11237 ND
	Cable – Rudder Trim Aft SAL-C2-CF-1443A	\$ 325.00 /each			C2CF1443A
	Cable – Elevator Trim Tab Fwd SAL-C2-CF-1567A	\$ 130.00 /each			C2CF1567AND, C2CF1563A
	Cable – Rudder Trim Fwd SAL-C2-CF-1569A	\$ 130.00 /each			C2CF1569AND, C2CF1461A
	Cable – Rudder Fwd SAL-C2-CF-741A	\$ 140.00 /each			C2CF741A, C2CF739ND
	Cable – Rudder Aft (pre-mod) SAL-C2-CF-745A	\$ 140.00 /each			C2CF745A, C2CF743ND
	Cable – Aileron in wing SAL-C2-CF-805	\$ 145.00 /each			C2CF805, C2CF809A
	Cable – Elevator upper SAL-C2-CF-817A	\$ 140.00 /each			C2CF817AND, C2CF813A
	Cable – Elevator lower SAL-C2-CF-819A	\$ 140.00 /each			C2CF819AND, C2CF815A

All prices quoted in Canadian Dollars, Taxes and freight not included in price.

\* Installation does not include paint or upholstery, or the cost of re-locating the battery (if necessary).

\*\* Sealand must do some work on customer's door. Does not include rear seatbelt anchors.

\*\*\* Installation does not include paint, or repairs required for proper install of kit.

AMO 103-90 / AO 103 – 90